

Tool Kit, Explosive Ordnance Disposal

SC: 1385-95-A20
NSN: 1385-01-267-8116
LIN: T00280

System Description

NSN 1385-01-267-8116 has been replaced by NSN 1385-01-487-8701. It is obsolete and should be reported as excess to the item manager for turn-in disposition.

This system is not currently in reset.

Reset Type

Reset Work (Field Level) - Work performed to correct equipment faults that are performed at the ORG/DS level; performed by unit level soldiers, augmented by contractor as required.

Reset Strategy

NSN 1385-01-267-8116 has been replaced by NSN 1385-01-487-8701.
It is obsolete and should be reported as excess to the item manager for turn-in disposition.

Reset Procedures

- Replace worn, broken, missing components IAW supply catalog.
- Reorder consumables IAW SC.

Reset Responsibility

Unit

Reset Location

This system is not currently in reset.

- Contact Information -

877.4.PMSKOT (877.476.7568)
rock-pm-skot@conus.army.mil